518 W. Montgomery Str	reet Henderson, NC 27536. Phone:(252)492-7541 Fax: (252) 431-1934
	Serving Industry Since 1952
INDUSTRIAL	8/3/2022
	Repair Quote Salesman Danny
Our S.O. No: 141318	Go Ahead No Fax / Email Date 9/23/22
To: Customer: Durham County Utility	
ATTN: Wade Shaw	Customer P.O. No. FR22-742
Fax No: 919-544-8590	Customer Ref. No.
E-mail : wshaw@dconc.gov;	Customer Data
Concernin	ng Repairs To Your Equipment
Manufacturer Davis EMU	H.P. 6 RPM 1140 Mount Asy Special
Model No Date CE 2004	K.W. Frame A.C.Volts 460
Type T17-6/16R	A.C Amps 9.7
Serial No <u>304340</u>	Assoc. Conn. Equip. TR75-2.17-6/16
Phase 3	
Application Mixer	
Work Needed:	
Upon inspection of the above unit, it was for enter the gearbox and motor. It was also for	ound that the mechanical seals had worn into the shafts allowing water to
Repairs will include: Disassemble, sandblast/clean and inspect parts, inspect for wear and measure bearing shaft and housing fits, steam and bake out stator, inspect and surge test winding, hi-pot test, build up and machine (2) seal surfaces, furnish and install new factory parts, new cord trumpet, new pencil electrode with 10m cord, new Wilo repair kit, consisting of; mechanical seals, bearings, lip seals, o-rings and misc. hardware, furnish and install new power cord and re-pot cord trumpet, reassemble, replace oil, test run and paint with 2-part marine black epoxy coating. (5-6 Weeks Delivery ARO)	
I have also included current pricing on a n	new replacement with a 4-6 Week delivery for your consideration
Thank you, Jacob Reed	
recorded all bearing information, tested Our labor cost involved so far in this def Above evaluation/inspection charges will be Your cost New Replacement \$ 11,516.51	
Please Let Us Know As S	oon As Possible Whether You Would Rather Repair Or Replace. oted, this job may be returned not repaired if not approved.

Fax Us At (252)-431-1934 Or Telephone Us At 800-232-7541

Attn:Patrick,Kristy,Shawn, Jacob Holland Industrial Is An Employee Owned Company (ESOP) Serving Industry Since 1952