



518 W. Montgomery Street Henderson, NC 27536. Phone:(252)492-7541 Fax: (252) 431-1934
 Serving Industry Since 1952

9/21/2022

Repair Quote

Our S.O. No: **141719**

Go Ahead No

Salesman **Danny**

Fax / Email Date **11/2/22**

To: Customer: **Durham County Utility Div. Triangle WWTP**

ATTN: **Wade Shaw**

Customer P.O. No. **FR22-742**

Fax No: **919-544-8590**

Customer Ref. No. **Tag#00589**

E-mail : **wshaw@dconc.gov**

Customer Data **TR75 Mixer. Train#1**

Concerning Repairs To Your Equipment

Manufacturer **Davis EMU**

H.P. **6**

RPM **1140**

Mount Asy **Special**

Model No **Date CE 2004**

K.W.

Frame

A.C.Volts **460**

Type **T17-6/16R**

A.C Amps **9.7**

Serial No **304334**

Assoc. Conn. Equip. **TR75-2.17-6/16**

Phase **3**

Mixer

Application **Mixer**

Work Needed:

The below mixer was disassembled and inspected and it was determined that the cause of failure was due to the bearings and seals wearing.
 The repair of the below will include:
 Disassemble, clean, steam clean and bake stator with winding, inspect and surge test winding, hi-pot test, measure shaft and housing bearing fits, furnish and install new bearings, (1) new inner and outer mechanical seal, new o-rings, new oil seals, (1) new moisture sensor, (1) new guard ring, (1) new cover over seal washer, (50') 14/7 power cord, pour cord cap, reassemble, replace oil, epoxy paint and test-run.
 (6-8 Weeks Delivery ARO due to parts).

Thank you for the opportunity to quote the above repair.

Shawn Gillespie

We have disassembled this machine, measured all bearing surfaces (shafts and endbells) for wear, recorded all bearing information, tested all windings for possible faults using BakerSurge Tester.

Our labor cost involved so far in this determination is \$ **420.00**

Above evaluation/inspection charges will be waived if this unit is repaired / replaced.

Your cost New Replacement
 \$ **11,632.50**



Total Repair Costs
 \$ **6,280.22**

The above prices are valid for 30 days and do not include freight or any necessary taxes. Please Let Us Know As Soon As Possible Whether You Would Rather Repair Or Replace. After 90 days of being quoted, this job may be returned not repaired if not approved.

Fax Us At (252)-431-1934 Or Telephone Us At 800-232-7541

Attn: Patrick, Kristy, Shawn, Jacob

Holland Industrial Is An Employee Owned Company (ESOP)

Serving Industry Since 1952